

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position (Horizontal: Z-axis/ Vertical:Y-axis)

X-axis




Y-axis



Z-axis



Test Configuration and peripherals



*Cabling and setup were taken into consideration and test data was taken under worse case conditions.

Description of EUT and Support equipment

No	Item	Model number	Serial number	Manufacturer	Remarks
A	Wireless Controller	CUH-ZCT1U	00226 for AT* 00238 for other tests	Sony Computer Entertainment	EUT
B	Laptop PC	2324A82(7P)	R9-W6R36 for AT* R9-X86LK for other tests	Lenovo	-
C	AC Adapter	45N0121	11S45N012Z1ZHXU2C B96T	Lenovo	-
D	Mouse	M-UB48	LZE02650788	Logitech	-
E	IN-EAR HEAD SET	-	-	Sony Computer Entertainment	-
F	Test Jig	-	-	Sony Computer Entertainment	-

*AT: Antenna Terminal Conducted test

List of cables used

No	Name	Length (m)	Shield		Remarks
			Cable	Connector	
1	USB Cable	1.5	Shielded	Shielded	-
2	DC Cable	1.8	Shielded	Shielded	-
3	AC Cable	1.0	Unshielded	Unshielded	-
4	USB Cable	0.8	Shielded	Shielded	-
5	IN-EAR HEAD SET Cable	1.2	Shielded	Shielded	-

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124