


**APPENDIX 1: Photographs of test setup**

**Spurious Emissions**  
**ipod (A1199) Transmitting mode**  
**Front**




**Rear**



**Spurious Emissions**  
**ipod (A1199) Transmitting + Charging mode**  
**Front**




**Rear**



**Spurious Emissions**  
**ipod (A1136) Transmitting mode**  
**Front**




**Rear**



**Spurious Emissions**  
**ipod (A1199) Transmitting + Charging mode**  
**Front**




**Rear**



**Spurious Emissions**  
**Network Walkman (NW-A805) Transmitting mode**  
**Front**




**Rear**



**Spurious Emissions**  
**Network Walkman (NW-A805) Transmitting + Charging mode**  
**Front**



**Rear**



**Worst Case Position**

**ipod (A1199) : (Hor : X-Axis, Ver : Z- Axis)**

**ipod (A1136) : (Hor : Y- Axis, Ver : Y- Axis)**

**Network Walkman (NW-A805) : (Hor : Y- Axis, Ver : Z- Axis)**


**X-Axis**



**Y-Axis**



**Z-Axis**



---

**UL Japan, Inc.**

**Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

MF060b(14.06.06)