




Inside view




No shield on the Bluetooth module





BT module



NFC module

