

MFA **M. Flom Associates, Inc. - Global Compliance Center**
3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176
www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

October 24, 2000

Federal Communications Commission,
via Electronic Filing

Attention: Steve Dayhoff
Equipment: FCC ID: ALH31103110 EA98738 Corr. 16709

Steve:

In reply to the referenced e-mail:

1. This Transmitter is intended as a Repeater. The device is normally rack-mounted. Its antenna is professionally installed in a fixed-mounted location, on an outdoor permanent structure.
2. The relevant pages of the Manual containing the R. F. Exposure statements are attached. Since this device is a repeater, it will NOT be used in a vehicle-mount configuration.
3. FYI: Thank you.

We trust the foregoing and attached now meet the requirements of the Commission.

Personal regards,



MORTON FLOM, P. Eng.

mf;mgf

cc: Applicant:

cc: A2LA Corrective Action file