


**EXHIBIT #9**

**INTERNAL PHOTOGRAPHS**

The following photographs are attached.

|   | <u>Exhibit</u> |
|---|----------------|
| 1. RF board <u>with</u> Shields (Top).                | 9A             |
| 2. RF board <u>without</u> Shields (Top).             | 9B             |
| 3. RF board <u>with</u> Shields (Bottom).             | 9C             |
| 4. RF board <u>without</u> Shields (Bottom).          | 9D             |
| 5. Vocon board <u>with</u> Shields (Top).             | 9E             |
| 6. Vocon board <u>without</u> Shields (Top).          | 9F             |
| 7. Vocon board <u>with</u> Shields (Bottom).          | 9G             |
| 8. Vocon board <u>without</u> Shields (Bottom).       | 9H             |
| 9. LTE Module board <u>with</u> Shields (Top).        | 9I             |
| 10. LTE Module board <u>without</u> Shields (Top).    | 9J             |
| 11. LTE Module board <u>with</u> Shields (Bottom).    | 9K             |
| 12. LTE Module board <u>without</u> Shields (Bottom). | 9L             |




Top Side RF board with Shields

**Applicant: Motorola Inc.**


**FCC ID: AZ489FT7059**

**IC: 109U-89FT7059**

EXHIBIT 9A




Top Side RF board without Shields




Bottom Side RF board with Shields






Bottom Side RF board without Shields




Top Side Vocon board with Shields




Top Side Vocon board without Shields






Bottom Side Vocon board with shields board




Bottom Side Vocon board without shields board




LTE Module board with shields board (Top)





LTE Module Board without shields (Top)





LTE Module Board with shields (Bottom)



LTE Module Board without shields (Bottom)