

Label Sample 1

RMN : TPN-C115  INPUT 19.5V  2.31A

CAN ICES-3(B)/NMB-3(B)

Made in China



Contains Broadcom Ralink Radio Model : BCM943142HM

Contains FCC ID: QDS-BRCM1063 CNC:C-10286

IC:4324A-BRCM1063 IFT No. RCPBRBC12-0020



SN:CNA209XXX www.hp.com



PN:AAAAAAA#ABA

Model:E13-1000 Warranty:1y1y0y

HP hs3110 HSPA
Mobile Broadband Module
IMEI: 3 5290 50 11234569

Contains Huawei Model MU736
Contains FCC ID: B94HNNHWR CNC:H-11670
SCT:RTIHUMU13-0137 IC:6369A-MU736



Label Sample 2

RMN : TPN-C115  INPUT 19.5V  2.31A

CAN ICES-3(B)/NMB-3(B)

Made in China



Contains Realtek Radio Model:RTL8723BE/RTL8723BE1T1R

Contains FCC ID: TX2-RTL8723BE CNC:C-12047

IC:6317A-RTL8723BE SCT:RCPRERT13-0876



SN:CNA209XXX www.hp.com



PN:AAAAAAA#ABA

Model:E13-1000 Warranty:1y1y0y

HP hs3110 HSPA
Mobile Broadband Module
IMEI: 3 5290 50 11234569

Contains Huawei Model MU736
Contains FCC ID: B94HNNHWR CNC:H-11670
SCT:RTIHUMU13-0137 IC:6369A-MU736

