



AIRSYS ATM INC.
Model: MK20ALOC
Photos Synthesizer PCB




ROGERS CONSULTING LABS, INC.
11701 Craig
Overland Park, KS 66210
hone/Fax: (913) 339-6072

AIRSYS ATM INC.
MODEL: MK20ALOC SN: ENGR2
Test #: 980610 FCC ID#: BOJ MK20ALOC
Test to: FCC Parts 2 and 87

AIRSYS ATM INC.
Model: MK20ALOC

Photo RF Board With Amplifiers Located at Top and Bottom and the
modulator at Center. No components located on backside.



ROGERS CONSULTING LABS, INC.
11701 Craig
Overland Park, KS 66210
hone/Fax: (913) 339-6072

AIRSYS ATM INC.
MODEL: MK20ALOC SN: ENGR2
Test #: 980610 FCC ID#: BOJ MK20ALOC
Test to: FCC Parts 2 and 87

Page 21 of 25