

**November 27, 2002**

**Federal Communications Commission  
Equipment Authorization Division,  
Applications Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21046**

**RE) FCC ID: BRWXR2i**

**To whom it may concern;**

**Please refer to the additional information listed below while reviewing the BRWXR2i System.**

- 1) Section 95.645 (b) states that plug-in crystals must not be accessible to the user. Indicate whether or not crystals are accessible to the user.**

Although the transmitter crystal is visible from the back of the transmitter, each crystal is glued in place prior to shipment making it a permanent installation. Consumer removal of the crystal will normally result in damage to the crystal. Therefore, frequency changes are done at the service center only.

- 2) The Manual must contain warnings per section 95.653**

A) Please refer to the manual attachment for this information

B) All content for operation is contained in the instruction manual.

1) All instructions are contained in the instruction manual.

2) There are no adjustments accessible to the user that would be in violation with the FCC rules.

3) This section is not applicable to our use.

**If there is any further information required, please contact me directly at:**

**Horizon Hobby Distributors  
ATTN: Len Sabato  
Fax: 217-355-0058  
Phone: 217-403-3588  
lsabato@horizonhobby.com**