



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 27, 2009

RE: FCC ID: CFS8DL5811_ATCB007437
Attention:

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the report needs to state under what FCC rule part testing has been performed. Please clarify what rule part for which certification is being requested. For example, if this is under 15.231 this must be made clear in the report.
2. Please note that it is not possible to determine what the information contained on page 2 of test report 5-3 means. What does this apply to and why is it in the report? Please explain and if part of the data please associate this data with the test results.
3. Please note that if this device is being certified under 15.231 please provide the following information: Please show compliance to 15.231(a)(2) is automatically activated; 15.231(a)(1) if manually activated.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Except as described in §0.459, correspondence and responses should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.