



LABELS

ACTUAL LOCATION OF LABEL ON BACK PLASTIC; BASIC CONFIGURATION - NO GSM OPTION:



THIS IS WHAT THE MAIN LABEL LOOKS LIKE IN THE GSM CONFIGURATION WITH THE AUXILIARY LABEL ADDED:



ENGINEERS DRAWINGS OF THE MAIN & AUXILIARY LABELS

**THIS IS THE MAIN LABEL:**

3.00"

1.625"

**LYNX TOUCH SERIES**

FCC ID: CFS8DLLYNXTOUCH1  
IC: 573F-LYNXTOUCH1

IC MODEL: LYNXTOUCH1

THIS DEVICE COMPLIES WITH PART 15 OF FCC RULES AND RSS 210 OF INDUSTRY CANADA. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIREED OPERATION.

COMPLIES WITH FCC RULES, PART 68 ACTA REGISTRATION NO. US: AC3AL05BL5000  
RINGER EQUIVALENCE: 0.5B

**Honeywell**

800-08126 1/11 Rev A

**THIS IS THE AUXILIARY LABEL:**

3.00"

0.75"

**LYNX TOUCH SERIES**

FCC ID: CFS8DLLYNXTOUCH1  
IC: 573F-LYNXTOUCH1

IC MODEL: LYNXTOUCHG1

CONTAINS TRANSMITTER MODULE

FCC ID: QIPMC55I

IC: 7830A-MC55I  
800-08334 2/11 Rev A

**THIS IS THE AUXILIARY LABEL PLACED OVER THE MAIN LABEL:**

3.00"

1.625"

**LYNX TOUCH SERIES**

FCC ID: CFS8DLLYNXTOUCH1  
IC: 573F-LYNXTOUCH1

IC MODEL: LYNXTOUCHG1

CONTAINS TRANSMITTER MODULE

FCC ID: QIPMC55I

IC: 7830A-MC55I  
800-08334 2/11 Rev A

THIS DEVICE COMPLIES WITH PART 15 OF FCC RULES AND RSS 210 OF INDUSTRY CANADA. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIREED OPERATION.

COMPLIES WITH FCC RULES, PART 68 ACTA REGISTRATION NO. US: AC3AL05BL5000  
RINGER EQUIVALENCE: 0.5B

**Honeywell**

800-08126 1/11 Rev A