







INTERNAL PHOTOGRAPHS OF EUT






DELL / DWRFID1202








DELL / DWRFID1202







DELL / DWRFID1202







DELL / DWRFID1202





























SMA Antenna








Compliance Certification Services Inc.


Report No.: T120216G02



Date of Issue: April 6, 2012







Yageo Antenna









Module

