






Power Measurement Setup














Sanos
Smart
Inspiron 1012

WLAN CRTU & WiMAX VaTu installed with Intel 6250 card(model 622ANXHMW)
Please do not run CRTU after VaTu, once WiMAX testing finished following steps apply:
4- Uninstall VaTu from corresponding folder (with WiMAX installer.exe)
5- Uninstall CRTU drivers from Win Device Manager
6- Re-install CRTU drivers from Win Device Manager by scanning new hardware
VaTu can be run after CRTU but it is recommended to uninstall CRTU drivers first.

sys



Smart
-TLB-Dell-Sanos-5486-