

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6115-2

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6125-2

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6125-2

Radiated Emission – Handset



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6115-2

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6115-2

Conducted Emission



Left Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6125-2

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: LS6125-2

Conducted Emission



Left Side View