


INTERTEK TESTING SERVICES

Internal photos – Model: CS6419-2

Base Unit assembly




Base Unit Main PCB comp side (View 1)




INTERTEK TESTING SERVICES

Internal photos – Model: CS6419-2

Base Unit Main PCB comp side (View 2)




Base Unit Main PCB solder side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6419-2

Base Unit Page Key front side




Base Unit Page Key rear side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6419-2

Base Unit Telephone Line and AC Jack front side




Base Unit Telephone Line and AC Jack rear side



INTERTEK TESTING SERVICES

Internal photos – Model: CS6419-2

Base Unit Oscillator PCB comp side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Base Unit assembly




Base Unit Main PCB comp side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Base Unit Main PCB solder side




Base Unit DAM front side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Base Unit DAM rear side




Base Unit Telephone Line and AC Jack front side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Base Unit Telephone Line and AC Jack rear side




Base Unit Oscillator PCB comp side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Handset assembly



Handset Main PCB comp side




INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Handset Main PCB display side (View 1)



Handset Main PCB display side (View 2)



INTERTEK TESTING SERVICES

Internal photos – Model: CS6429-2

Handset Oscillator PCB comp side

