

6.4.4 Photos of Conduction Measuring Setup

Model: 28811XXX-A

Mode: Base On Line



Model: 28811XXX-A

Mode: Base Charging& Stand by



Model: 28821XXX-A

Mode: Base On Line



Model: 28821XXX-A

Mode: Base Charging& Stand by



6.13.4 Photos of Radiation Measuring Setup

Model 28811XXX-A

Mode: Base On Line



Model: 28811XXX-A

Mode: Base Charging& Stand by



Model 28821XXX-A

Mode: Base On Line



Model: 28821XXX-A

Mode: Base Charging& Stand by

