Acer Incorporated

8F, 88, Sec 1, Hsin Tai Wu Rd, Hsichih, Taipei Hsien, Taiwan Tel: 886-2-6606-3131 Ext: 3811; Fax: 886-2-2696-3535

Federal Communications Commission Authorization and Evaluation Division 1435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

This device with FCC ID: HLZ7265D2W; IC: 1754F-7265D2W integrates a WLAN/BT module:

	Model Name	FCC ID	IC
WLAN/BT module	7265D2W	PD97265D2	1000M-7265D2

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D01v02, the original Intel Mobile Communications modular report are submitted to represent the compliance of Part 15C(RSS-210)/15E(RSS-210) conducted RF testing items of this device.

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Should you have any comments or questions, please feel free to contact me.

Sincerely,

RU Jan

Ru.jan@acer.com

RuIn