

Label shown is a sample.
FCC ID will vary: HSXWH04

DE1765

FCC ID: HSXWH01

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation.

COMPASS CALIBRATION

Put detector in a LEVEL position.
Press BOTH volume buttons (Λ and V)
simultaneously.

Carefully drive vehicle in TWO COMPLETE
CIRCLES.

If calibration does not automatically finish,
press both Λ and V buttons simultaneously
to complete calibration.

If error occurs, repeat process.

If error repeats:

- Verify that detector is level.
- Move detector to a new location.
- Repeat calibration in new
driving location.
- Call 1-800-531-0000