


Internal Photos

Component side




3-Button type



2-Button type

Solder side



Note:

The difference in the number of switches has no influence on RF performance.