FCC ID: I88NBG6716

## **Description of Permissive Change**

The report is prepared for FCC class II permissive change. The difference compared with original report is changing following component. For more detail, please refer to as below.

Item	Description
USB Connector	Changed source to CONN USB-A_2.0 1PORT USB-AFRA122-088 DIP LFP
X'tal of PHY	Changed source to X'TAL 25MHz 25ppm 20pF NXS25.000AD20F DIP LFP
2.4GHz I-PEX connector	Changed source to RFJACK COAXIAL F 180 Wp8-5801-002-00-810 SMD LFP
IC ROM-FLASH	Changed from 128Mb to 32Mb
IC ROM-FLAS	Changed from 2 GB to 1GB
WAN Port	Changed to without metal case
LAN Port	Changed to without metal case
DDR	DDR updated version

Please refer to test repots for more details about the test items.

Reference no.: RF140124C06