



Internal Photographs for GTX 330D





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

GARMIN INTERNATIONAL, INC.
MODEL: GTX 330D, 011-00455-()
Test #: 020326
Test to: FCC Parts 2 and 87

FCC ID: IPH-0046400

Page 1 of 5

GTX330DTsup.doc 4/9/2002





ROGERS LABS, INC.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214

GARMIN INTERNATIONAL, INC.
 MODEL: GTX 330D, 011-00455-()
 Test #: 020326
 Test to: FCC Parts 2 and 87

FCC ID: IPH-0046400

Page 2 of 5

GTX330DTsup.doc 4/9/2002





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

GARMIN INTERNATIONAL, INC.
MODEL: GTX 330D, 011-00455-()
Test #: 020326
Test to: FCC Parts 2 and 87

FCC ID: IPH-0046400

Page 3 of 5

GTX330DTsup.doc 4/9/2002




ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

GARMIN INTERNATIONAL, INC.
MODEL: GTX 330D, 011-00455-()
Test #: 020326
Test to: FCC Parts 2 and 87

FCC ID: IPH-0046400

Page 4 of 5

GTX330DTsup.doc 4/9/2002



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

GARMIN INTERNATIONAL, INC.
MODEL: GTX 330D, 011-00455-()
Test #: 020326
Test to: FCC Parts 2 and 87

FCC ID: IPH-0046400

Page 5 of 5

GTX330DTsup.doc 4/9/2002