




Internal photographs of transmitter section of equipment under test.
Inside with unit opened.




Transmitter board.



Transmitter printed circuit board solder side.





ROGERS LABS, INC.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: Nuvi 310/360
Test #:060221
Test to: FCC Parts 2 and 15.249, RSS-210

SN: 1201
GPN:011-01404-xx
FCC ID#: IPH-01081 IC:1792A-01081
Page 3 of 3