

## **Tune-up Procedure**

Each unit will undergo Bluetooth testing in our factory. Any units unable to pair with a test fixture will be marked as failures. These will be scrapped or reworked at our discretion. The maximum output power is set via a register in the Bluetooth IC. This has been tested to be inside a valid range with adequate headroom for all expected combinations of Bluetooth radio and Balun+Filter parts.