

Tune-up Procedure

Transmitter tune-up procedure

Each unit is tested during unit production by measuring the output strength. The unit is then given pass/fail status based on the measured parameters. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and removing non-compliant units.