



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-0121611
Test: 180320
Test to: 47CFR Parts 2 and 87
File: IPH0225611 TNB Short Term Conf TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-0225611
Date: June 20, 2018
Page 1 of 3





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-0121611
Test: 180320
Test to: 47CFR Parts 2 and 87
File: IPH0225611 TNB Short Term Conf TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-0225611

Date: June 20, 2018

Page 2 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-0121611
Test: 180320
Test to: 47CFR Parts 2 and 87
File: IPH0225611 TNB Short Term Conf TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-0225611

Date: June 20, 2018

Page 3 of 3