



Garmin International, Inc.
1200 East 151st Street
Olathe, Kansas 66062
P: 913-397-8200 F: 913-397-8282

May 29, 2015

Mr. Scot D. Rogers

Rogers Labs, Inc.

4405 West 259th Terrace

Louisburg, KS 66053

Re: FCC ID: IPH-02293/ IC: 1792A-02293 Identifier location

Mr. Rogers,

Regarding the location of the FCC and Industry Canada Identifiers for IPH-02293/ IC: 1792A-02293, Garmin believes that the location of the identifiers is permanently attached to the unit. The identifiers are located on the far end of the mounting strap. The identifier are molded into the strap material and are therefore part of the strap. The unit is mechanically affixed to the mounting strap. The mounting strap must be used in order for accurate data to be collected by the unit. The unit will not provide the end-user accurate data if separated from the mounting strap. The unit is intended to be only operated while attached to the mounting strap. When used as intended, the unit will be connected to the strap which contains the identifiers.

If you have any questions or concerns, please feel free to contact the undersigned.

Sincerely,

A handwritten signature in cursive script that reads "John A. Farley".

John Farley

Lead Compliance Engineer