



Internal Photographs of transmitter
Shields removed



Shields in place




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


Garmin International, Inc.
Model: A02546
Test #: 160113
Test to: CFR47 Parts 2, 80, RSS-238
File: A02546 IntPho

FCC ID: IPH-02546
IC: 1792A-02546
SN: FF-ENG#2
Date: February 14, 2016
Page: 1 of 2

Shields removed



Shields in place



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02546
Test #: 160113
Test to: CFR47 Parts 2, 80, RSS-238
File: A02546 IntPho

FCC ID: IPH-02546
IC: 1792A-02546
SN: FF-ENG#2
Date: February 14, 2016
Page: 2 of 2