




Test setup photographs



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02643
Test #: 150119
Test to: CFR47 (15C), RSS-210
File: Short Term Conf TSUP A02643


SN: 3897367003
FCC ID#: IPH-02643
IC: 1792A-02643
Date: June 15, 2015
Page 1 of 5



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02643
Test #: 150119
Test to: CFR47 (15C), RSS-210
File: Short Term Conf TSup A02643

SN: 3897367003
FCC ID#: IPH-02643
IC: 1792A-02643
Date: June 15, 2015
Page 2 of 5




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02643
Test #: 150119
Test to: CFR47 (15C), RSS-210
File: Short Term Conf TSup A02643

SN: 3897367003
FCC ID#: IPH-02643
IC: 1792A-02643
Date: June 15, 2015
Page 3 of 5





Rogers Labs, Inc.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Garmin International, Inc.
 Model: A02643
 Test #: 150119
 Test to: CFR47 (15C), RSS-210
 File: Short Term Conf TSup A02643

SN: 3897367003
 FCC ID#: IPH-02643
 IC: 1792A-02643
 Date: June 15, 2015
 Page 5 of 5