



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02895
Test #: 160919
Test to: CFR47 15C, RSS-210
File: A02895 Short Term Conf TSup

SN's: 4RF200022, 4RF300010
FCC ID: IPH-02895
IC: 1792A-02895
Date: July 5, 2017
Page 1 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02895
Test #: 160919
Test to: CFR47 15C, RSS-210
File: A02895 Short Term Conf TSup

SN's: 4RF200022, 4RF300010
FCC ID: IPH-02895
IC: 1792A-02895
Date: July 5, 2017
Page 2 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02895
Test #: 160919
Test to: CFR47 15C, RSS-210
File: A02895 Short Term Conf TSup

SN's: 4RF200022, 4RF300010
FCC ID: IPH-02895
IC: 1792A-02895
Date: July 5, 2017
Page 3 of 3