

Tune-up Procedure

Each unit is tested during unit production by measuring the output strength. The unit is then given pass/fail status based on the measured output strength. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.

Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: A02947
Test #: 150828
Test to: CFR47 15C, RSS-247
File: A02947 TunPro

SN: 3908535043
FCC ID#: IPH-02947
IC: 1792A-02947
Date: October 1, 2015
Page 1 of 1