



Front no shield



Back no shield

Antenna Connection Point




Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03504  
Test #: 180626  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03504 Short Term Conf IntPho


SN's: 39729 61850 / 39729 61852  
FCC ID: IPH-03504  
IC: 1792A-03504  
Date: October 18, 2018  
Page 1 of 3

Front



Back

Antenna Connection Point



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03504  
Test #: 180626  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03504 Short Term Conf IntPho

SN's: 39729 61850 / 39729 61852  
FCC ID: IPH-03504  
IC: 1792A-03504  
Date: October 18, 2018  
Page 2 of 3

Antenna Location



Inside case



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03504  
Test #: 180626  
Test to: CFR47 15, RSS-210, RSS-247  
File: A03504 Short Term Conf IntPho

SN's: 39729 61850 / 39729 61852  
FCC ID: IPH-03504  
IC: 1792A-03504  
Date: October 18, 2018  
Page 3 of 3