

Tune-up Procedure

Each unit is tested during unit production by measuring the output strength. The unit is then given pass/fail status based on the measured output strength. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.

Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: AA2758
Test #: 150715
Test to: CFR47 (15C), RSS-210
File:AA2758 TunPro

SN: 63494
FCC ID#: IPH-A2758
IC: 1792A-A2758
Date: September 5, 2015
Page 1 of 1