


Annex A3


Conducted Spurious Emissions

with TDMA Modulation


138.025 MHz_TDMA_1 - 10 GHz




138.025 MHz_TDMA_30 - 1000 MHz




150.8125 MHz_TDMA_1 - 10 GHz




150.8125 MHz_TDMA_30 - 1000 MHz




158.07 MHz_TDMA_1 - 10 GHz




158.07 MHz_TDMA_30 - 1000 MHz




161.625 MHz_TDMA_1 - 10 GHz




161.625 MHz_TDMA_30 - 1000 MHz




161.800 MHz_TDMA_1 - 10 GHz




161.800 MHz_TDMA_30 - 1000 MHz




173.975 MHz_TDMA_1 - 10 GHz




173.975 MHz_TDMA_30 - 1000 MHz




380.025 MHz_TDMA_1 - 10 GHz




380.025 MHz_TDMA_30 - 1000 MHz




406.2 MHz_TDMA_1 - 10 GHz




406.2 MHz_TDMA_30 - 1000 MHz




420 MHz_TDMA_30 - 1000 MHz




420.0 MHz_TDMA_1 - 10 GHz




429.975 MHz_TDMA_1 - 10 GHz




429.975 MHz_TDMA_30 - 1000 MHz




450.025 MHz_TDMA_1 - 10 GHz




450.025 MHz_TDMA_30 - 1000 MHz




459.65 MHz_TDMA_1 - 10 GHz




459.65 MHz_TDMA_30 - 1000 MHz




467.825 MHz_TDMA_1 - 10 GHz




467.825 MHz_TDMA_30 - 1000 MHz




469.975 MHz_TDMA_1 - 10 GHz




469.975 MHz_TDMA_30 - 1000 MHz




511.975 MHz_TDMA_1 - 10 GHz




511.975 MHz_TDMA_30 - 1000 MHz




519.025 MHz_TDMA_30 - 1000 MHz




519.975 MHz_TDMA_1 - 10 GHz




768.025 MHz_TDMA_1 - 10 GHz




768.025 MHz_TDMA_30 - 1000 MHz




769.025 MHz_TDMA_1 - 10 GHz




769.025 MHz_TDMA_30 - 1000 MHz




774.975 MHz_TDMA_1 - 10 GHz




774.975 MHz_TDMA_30 - 1000 MHz




775.975 MHz_TDMA_1 - 10 GHz




775.975 MHz_TDMA_30 - 1000 MHz




798.025 MHz_TDMA_1 - 10 GHz




798.025 MHz_TDMA_30 - 1000 MHz




799.025 MHz_TDMA_1 - 10 GHz




799.025 MHz_TDMA_30 - 1000 MHz




804.975 MHz_TDMA_1 - 10 GHz




804.975 MHz_TDMA_30 - 1000 MHz




805.975 MHz_TDMA_1 - 10 GHz




805.975 MHz_TDMA_30 - 1000 MHz




806.025 MHz_TDMA_1 - 10 GHz




806.025 MHz_TDMA_30 - 1000 MHz




810.025 MHz_TDMA_1 - 10 GHz




810.025 MHz_TDMA_30 - 1000 MHz




814.975 MHz_TDMA_1 - 10 GHz




814.975 MHz_TDMA_30 - 1000 MHz




823.975 MHz_TDMA_1 - 10 GHz




823.975 MHz_TDMA_30 - 1000 MHz




851.025 MHz_TDMA_1 - 10 GHz




851.025 MHz_TDMA_30 - 1000 MHz




855.025 MHz_TDMA_1 - 10 GHz




855.025 MHz_TDMA_30 - 1000 MHz




859.975 MHz_TDMA_1 - 10 GHz



859.975 MHz_TDMA_30 - 1000 MHz



868.975 MHz_TDMA_1 - 10 GHz



868.975 MHz_TDMA_30 - 1000 MHz

