

Date

4. February 2020



To whom this may concern,

Phonak Virto M90-312 left	Base device
Phonak Virto M70-312 left	Identical hardware to base device, only a different SW parameter
Phonak Virto M50-312 left	Identical hardware to base device, only a different SW parameter
Phonak Virto M30-312 left	Identical hardware to base device, only a different SW parameter
Phonak Virto M90-312 Right	Base device
Phonak Virto M70-312 Right	Identical hardware to base device, only a different SW parameter
Phonak Virto M50-312 Right	Identical hardware to base device, only a different SW parameter
Phonak Virto M30-312 Right	Identical hardware to base device, only a different SW parameter

The hardware of all articles described above is identical to the respective base device. The only difference is the software image reflecting the price levels set at 90, 70, 50 and 30.

The performance levels include only a differential set of features to support certain listening conditions.

Faithfully,

A handwritten signature in blue ink, appearing to read "GB", is written over a horizontal line.

Glenn Borrett
Senior Regulatory Affairs Manager

Sonova AG
Laubisrütistrasse 28
8712 Stäfa
Switzerland

Phone +41 58 928 01 01
Fax +41 58 928 20 11
info@sonova.com
www.sonova.com