

See Manual Before Use
Voir Manuel Avant Usage

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: 1) This device may not cause harmful interference, 2) This device must accept any interference received, including interference that may cause undesired operation.



LISTED
E145532



ATTENTION
OBSERVE PRECAUTIONS
FOR HANDLING
ELECTROSTATIC
SENSITIVE DEVICES
E134



E134

<http://cisco-returns.com>

LISTED AS I.T.E. FOR USE IN HAZARDOUS LOCATIONS

Class I, Div 2, Groups A B C D
Class I, Zone 2, Ex na IIC T4 Gc
CE II 3 G, Ex na IIC T4 Gc
DEMKO 14 ATEX 1358X
Class I, Zone 2, AEx na IIC T4 Gc

Country of Origin Mexico
Cisco Systems, Inc.
170 W. Tasman Dr, San Jose, CA USA

MODEL: IR509UWP-915
FCC ID: LDK-IR509UWP
IC: 2461B-IR509UWP

PID VID: IR509UWP-915/K9 V01

TAN: 68-5082-01 A0

SN: JMX1837X000