



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134

August 28, 2013

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Cisco Systems will establish a new FCC ID: LDK102087P under Cisco Systems grantee code for purpose of marketing. The original grant to Cisco Systems will remain in effect.

Per 2.933(b)

1. The original identification is LDK102087
2. The original grant date is 08/15/2013
3. The equipment is electrically identical. Only the model name and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. The purpose of the change of ID is to add anew model that will be marketed for indoor and outdoor use with progressional installation. A C2PC will be filed once that change in ID has been granted to modify that grant conditions to limit this new version to professional installation
6. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Best Regards

A handwritten signature in blue ink, appearing to read "Jim Nicholson".

Jim Nicholson
Compliance Engineer
Cisco Systems, Inc