

Kare Oksanen

15 January 2007

1. Please note that both the 850MHz band and the 1900MHz band need MPE calculations. The MPE report provided appears only to address the 850MHz band. Please provide the MPE calculations for the 1900MHz band.

**1900MHz band was originally omitted as both limit is higher and power output lower than those of 850MHz band. However, document is now revised to include also 1900MHz data.**

2. Please note that the FCC has stated that for licensed modular transmitters "A licensed module must have an FCC ID label on the module itself, visible through a window on the final device or when an access cover is easily removed; if not visible, a second label must be placed on the outside of the final product stating: "Contains FCC ID: xxxxxxxx". Please note that the manual does not appear to instruct the OEM of this requirement. Please provide information on how this is relayed to the OEM (i.e. manual instructions etc).

**Handling guidelines –document is now updated to include this information.**

3. FYI – Please note that devices of this type (i.e. with antenna connectors) are to have the conducted power levels listed on the grant. This is to let you know that the conducted power levels in the report will be the power levels listed.

**Acknowledged. We have updated both 731 and RSP-100 forms accordingly.**