


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone CDMA Input IN RACK
FFPA-8689-120

Tested By: BDeL 10/19/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone - CMA Output IN RACK
FFPA-8689-120

Tested By: B. Del 10/4/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone TDMA Input IN RACK
FFPA-8689-120

Tested By: B. DeF 10/4/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone DDM A Output IN RACK
FFPA-8689-120

Tested By: B. DeL. 10/4/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120




Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone AMPS OUTPUT IN RACK
FFPA-8689-120

Tested By: B. DeF 11/19/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120




Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: 2FSK output IN RACK
FFPA-8689-120

Tested By: BDL