

FCC SUPERSEDE EXHIBIT LETTER. 20110628

Exhibit AC313U_FCC_Parts_22_24_27_Test_Report_Rev2.pdf

has been superseded by

AC313U_FCC_Parts_22_24_27_Test_Report_Rev3.pdf.

The reason is the during the final upload process, due to administrative error, AC313U_FCC_Parts_22_24_27_Test_Report_Rev3.pdf, was not placed in the upload files area. AC313U_FCC_Parts_22_24_27_Test_Report_Rev2.pdf was mistakenly uploaded to the final filing.

Changes to the Rev3 report were based on questions from FCC and the TCB during the PBA process. The revisions include updated LTE output power results on pages 16-18.

AC313U_FCC_Parts_22_24_27_Test_Report_Rev3.pdf is the latest revision of the conducted measurements report and contains measurements that are consistent with the results in the SAR Report 10U13530-D FCC IC LTE SAR Report_No Photos.pdf which was uploaded with the final filing.