







ATTACHMENT D: TEST PLOTS

Conducted Spurious CDMA Ch. 1013


Conducted Spurious CDMA Ch. 0384



Conducted Spurious CDMA Ch. 0777

Power Out. CDMA Ch. 1013






Power Out. CDMA Ch. 0777




Power Out. CDMA Ch. 0384**Channel Power. CDMA Ch. 0384**

Occupied Bandwidth. CDMA Ch. 0384






Band Edge. CDMA Ch. 1013**Band Edge. CDMA Ch. 0777**

Band Edge - Block a. CDMA Ch. 0310




Band Edge - Block b. CDMA Ch. 0357




Band Edge - Block a. CDMA Ch. 0643.**Band Edge - Block b. CDMA Ch. 0690**

Band Edge - Block a. CDMA Ch. 0693



Band Edge - Block b. CDMA Ch. 0740



FCC ID: NPQFCS8900
Manufacturer: Telian Coporation
Channel: 869.0 ~ 894.0 MHz
Test Mode: CDMA Receiving Band

