

Report No.: 0306682
Model No.: 13978

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

PLT: 9.44ms


0.00dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: LR
(Leah Wang)
Date: 10/6/03

Checked By: Anthony Chen
(Anthony Chen)
Date: 11/6/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 40ms

F: 49.860000MHz

Report No.: 0306682
Model No.: 13978

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

DLT: 9.40ms


0.16dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.860000MHz

Tested By: LA

James Wang

Date: 10/6/03

Checked By: [Signature]

Anthony Chan

Date: 11/6/03

Test Result : Pass / Fail / NA

Report No.:

Model No.:

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 760us

-0.17dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.860000MHz

Tested By: LL
(Kevin Wong)Date: 10/6/03Checked By: [Signature]
(Anthony Chan)Date: 11/6/03Test Result: Pass / Fail / NA

Report No.:

Model No.:

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

DLT: 240us


-0.10dB

RB 3MHz#

AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 20ms

F: 49.860000MHz

Tested By: LK

(Kerik Wong)

Date: 10/6/03Checked By: [Signature]

(Anthony Q. A.)

Date: 11/6/03Test Result: Pass / Fail / NA