



Intertek Testing Services

ETL SEMKO

Report No.: **01005701**
Mode: Talk

Tested By: Hong, Report No.: **01005701**

Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450k	30M	5k	10k	PK	20ms	AUTO LN OFF 60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: **01005701**
Mode: Talk

Tested By: Hong, Report No.: 01005701

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

no Results

Ctrl No.: N/A