

May 18, 2012

Hello

1. The following is the response received to your questions:
  - 1.1. The sizes of the Indoor enclosure and the Outdoor enclosure are different. Please see attached DS that includes this data.
  - 1.2. Connectors that are installed on the internal electronics were not changed. Connectors on the enclosure panel were changed (due to different external packaging).
  - 1.3. Only Power Supply was changed to meet wider temperature range. All the rest of electronics were unchanged.
  - 1.4. Both Indoor and Outdoor units present in the attached Data Sheet. The outward appearance has been changed.
  - 1.5. The placement of electronic modules inside new Outdoor enclosure was changed in order to optimal fit the new outdoor housing. Electronics inside the modules were not changed.
  - 1.6. Outdoor enclosure does not include any additional controls.
  - 1.7. Electrical circuitry is identical to the original design.
2. Please let us know ASAP if you need any additional information.

Regards,

**David Shidlovsky** | Technical Writer

Address 1 Bat-Sheva St. POB 87, LOD 71100 Israel

Tel 972-8-9186113 Fax 972-8-9153101

Mail [emc@itl.co.il](mailto:emc@itl.co.il)/[davids@itl.co.il](mailto:davids@itl.co.il) Web [www.itl.co.il](http://www.itl.co.il)

[Fill out Customer Satisfaction Survey](#)

## ***Global Certifications You Can Trust***



Save a tree. Do not print this message if not really necessary.