

9. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION

X-AXIS PHOTO



Y-AXIS PHOTO






RADIATED RF MEASUREMENT SETUP
WORST-CASE: Z-AXIS WITH AC ADAPTER


Z-AXIS RADIATED FRONT PHOTO



Z-AXIS RADIATED FRONT PHOTO



POWER-LINE CONDUCTED EMISSIONS MEASUREMENT SETUP



END OF REPORT