

Appendix C – SAR Test Setup Photos




Test Position Back 0 mm Gap

Note: All cables removed prior to testing.



Test Position Bottom 0 mm Gap

Note: All cables removed prior to testing.



Test Position Laptop 0 mm Gap

Note: All cables removed prior to testing.



Front of Device Tablet Mode



Back of Device Tablet Mode



Laptop Mode