



Test Setup Photos

FOR:

Internet Location Manager

MODEL #: iLM3170-W, iLM3175-W, iLM3177-WG

**@Road, a Trimble Company
47071 Bayside Pkwy.
Fremont, CA 94538**

FCC ID: PDC-ILM317XSW

IC ID: 5079A-ILM317X

**TEST REPORT #: EMC_ATROA_006_07002_FCC15_247WLAN
DATE: 2007-07-05**



Certificate # 2135.01



**FCC listed:
A2LA accredited**

**IC recognized #
3462B**

CETECOM Inc.

411 Dixon Landing Road • Milpitas, CA 95035 • U.S.A.

Phone: + 1 (408) 586 6200 • Fax: + 1 (408) 586 6299 • E-mail: info@cetecomusa.com • <http://www.cetecom.com>

CETECOM Inc. is a Delaware Corporation with Corporation number: 2113686

Board of Directors: Dr. Harald Ansorge, Dr. Klaus Matkey, Hans Peter May

© Copyright by CETECOM

Table of Contents

1	ASSESSMENT	3
2	TEST SETUP PHOTOS	4
2.1	RADIATED SPURIOUS EMISSIONS	4
2.2	RADIATED SPURIOUS EMISSIONS	5
2.3	RADIATED SPURIOUS EMISSIONS	6

1 Assessment

The following is in compliance with the applicable criteria specified in FCC rules Parts 2, and 15 of Title 47 of the Code of Federal Regulations.


Company	Description	Model #
@Road, A Trimble Company	Internet Location Manager	iLM3170-W, iLM3175-W, iLM3177-WG

Date:2007/07/10


Name: Peter Mu
Title: Project Engineer
Company: Cetecom Inc.
Address: 411 Dixon Landing Rd, Milpitas, CA 95035, USA
Phone: +1 408 586 6221
Email: peter.mu@cetecomusa.com

2 TEST SETUP PHOTOS

2.1 RADIATED SPURIOUS EMISSIONS



2.2 RADIATED SPURIOUS EMISSIONS



2.3 RADIATED SPURIOUS EMISSIONS

