

Nemko Korea CO., Ltd.

300-2, Osan-Ri, Mohyun-Myun, Yongin-City, Kyungki-Do, KOREA


TEL:+82 31 322 2333

FAX:+82 31 322 2332

FCC PART 15 Class II Permissive Change

- 1. Applicant:** XENON Telecommunications Co., Ltd.
Kayang Techno Town 203, Kayang-3Dong, 1487, Kangsea-Ku,
Seoul, Korea
Attn : Mr. J. G. Jung
- 2. Date of Issue:** July 24, 2001
- 3. Test Report no.:** NK2BE355
- 4. Test Site:** Nemko Korea Co., Ltd., EMC site in Korea
- 5. FCC ID:** PNAXEN-1810E
- 6. Description of the Changes according to FCC part 2.1043**
 - 6.1 Change artwork of the Main board**
DS90C387AVJD(U14), 74HCT14DR(U11),FDC6326L(U2, U6,U16), L1117L-3.3(U1,U3,U12,U13,U19)
CA24WC16J(U6), KIA7805AF(U5), EMX1(U7), MTV212MV32(U9), 14.318MHz(Y1), 12MHz(Y2)
 - 6.2 Change artwork of the Knobs board**
 - 6.3 Change artwork of the Interface board**
 - 6.4 Delete the TV Tuner board**
 - 6.5 Delete the Audio board**

*) The Class II permissive change, as detailed above, was made and the test report was attached.



Verified By : H.H. Kim

Manager & Chief Engineer

XENON Telecommunications Co., Ltd.

FCC ID:PNAXEN-1810E