

Prepared by
SEM/BGLIVM Kent Lorentzon + 46 46 36 90 43
Contents responsible if other than preparer

Document number
BGLI08:548
Date
2008-06-30
Remarks

Revision
A

Approved by
SEM/BGLIVMC Peter Lindeborg + 46 46 212 6180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

**Application: PY7A1052171,
4170B-A1052171.**

Statement on Bluetooth hardware

Sony Ericsson mobile phone G502c (FCC ID: PY7A1052171, IC: 4170B-A1052171) uses the exact same Bluetooth hardware and software as G502 (FCC ID: PY7A3022121, IC: 4170B-A3022121).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-21-06/08, dated 2008-05-03) issued for G502 also applies for G502c.

Best regards,



Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund