



Sony Ericsson

Confidential

1(1)

Prepared by

SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Document number

CVDVBA11:342

Date

2011-07-14

Remarks

Revision

A

Approved by

SEMC/CVDVBA Håkan Sjöberg +46 10 80 13559

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number: AAD-3880106-BV,

FCC ID: PY7A3880106,

Canada IC: 4170B-A3880106

Statement on Bluetooth hardware

Sony Ericsson mobile phone ST15a (FCC ID: PY7A3880106, IC: 4170B-A3880106) uses the exact same Bluetooth hardware and software as ST15i (FCC ID: PY7A3880107, IC: 4170B-A3880107).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-2977-40-04/11, dated 2011-06-06) issued for ST15i also applies for ST15a.

Best regards,

Håkan Sjöberg
Acting Manager – HW Verification
Global Type Approval
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 010-80 00000
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 010-80 02040
Int +46 10 80 02040