

Annex 3: Photos of test set-up
to TEST REPORT
No.: 2-0004-11-18-1i

According to:
FCC Regulations
Part 15.109
Part 15.207 & 15.209 & Part 15.247
IC Regulations
RSS-Gen, Issue 3
RSS-210: Issue 8

for

Sony Ericsson Mobile Communications AB

Mobile phone AAD-3880121-BV

FCC-ID: PY7A3880121
IC: 4170B-A3880121


Laboratory Accreditation and Listings			
 Deutsche Akkreditierungsstelle D-PL-12047-01-01	 Reg. No.: 736496 MRA US-EU 0003	 Industry Canada Reg. No.: 3462D-1 Reg. No.: 3462D-2 Reg. No.: 3462D-3	 Voluntary Controls for Electromagnetic Emissions Reg. No.: R-2665, R-2666 C-2914, T-1967, G-301
 AUTHORIZED RF LABORATORY	 LAB CODE 20011130-00		
accredited according to DIN EN ISO/IEC 17025			
<p align="center"> CETECOM GmbH Laboratory Radio Communications & Electromagnetic Compatibility Im Teelbruch 116 • 45219 Essen • Germany Registered in Essen, Germany, Reg. No.: HRB Essen 8984 Tel.: + 49 (0) 20 54 / 95 19-954 • Fax: + 49 (0) 20 54 / 95 19-964 E-mail: info@cetecom.com • Internet: www.cetecom.com </p>			




Table of contents

1. PHOTOS OF TEST SET-UP3


1. Photos of test set-up



Photograph 1: Conducted test set-up: conducted RF-measurements



Photograph 2: Radiated test set-up: radiated RF-measurements



Photograph 3: Conducted test set-up, emissions on AC-mains