

Subject: Revised of Cisco-Linksys, FCC ID:Q87-HGA7S-3
To: tjohnson@AmericanTCB.com
Cc: stephanie@adt.com.tw
From: wendy@adt.com.tw

Dear Timothy R. Johnson,

1. We have been revised the confidentiality requires letter and parts list again.
2. The manufacturer on Part lists detailed as below:

We use Intersil Frisbee chipset for FCC ID: Q87-HGA7S-3
please have the following information

| | |
|------------|--------|
| ISL3686AIR | RF |
| ISL3084IR | VCO |
| ISL3880IK | BB/MAC |
| ISL3980IR | PA |

3. The antenna gain is 7dBi, so the EUT photo only show it for both mode A and mode B.

When the antenna separated from EUT (with antenna stand), the antenna will lose 2dBi gain,

so we mentions +5dBi gain antennas in the RF exposure and we tested 5dBi gain antenna in the test report.

Thanks for your assistance!

Best Regards,
Wendy